

### **Inspection Form**

#### Form WMSC-IR-1

### Washington Metrorail Safety Commission

#### 0145Agency/Department Information

Inspection Date	YYYY	MM	DD	Report Number	20191116-WMATA-KEK-4				
Inspection Date	2019	11	16	Report Number					
Rail Agency Name	Washington Metropolitan Area Transit Authority			Rail Agency Department	WMATA - ATC	Sub- Department		ATC	
	Name			Email	Office Phone		Mobile Phone		
Rail Agency Department									
Contact Information									
Inspection Location	Shady Grove	Yard – A99							

#### **Inspection Summary**

Inspection Activity #	1	2	3	4	5	6
Activity Code	STC-OBS-RM	NA	NA	NA	NA	NA
Inspection Units	1-37Conductor					
Inspection Subunits	0					
Defects (Number)	0					
Recommended Finding	0					
Remedial Action Required <sup>1</sup>	NO					
Recommended Reinspection	NO					

#### **Activity Summaries**

Inspection Activity #	1 Inspection Subject 10 Year			Testing Cable Merging			Activity Code		STO	С	OBS	RM		
Job Briefing Employee Name/Title	WMATA RWIC - #2254, "AA"				Accompanied Inspector?		YES	Out Brief Conducted	YES	Time	0145	am	Outside Shift	YES
Related Reports	N/A			Related CAPS / Findings N/A										
	Ref Rule o			Rule or S	or SOP Standard				Other / Title			Checklist Reference		
Related Rules, SOPs, Standards, or Other	RWPM							ATC-100	ATC-1001		Form 1001-1			
Standards, or Other							ATC-2000 Sys Integra		gra					
Inconcetion Location	Main Track	Yard	Statio	on (	occ	RTA Facility	WMSC Office	Track Trace	At-grad	e Tur	unnel l		vated	N/A
Inspection Location		х						Track Type	х					
line/a)	A 1:	Track		Yard Traks Chain Marker and/or Statio		rker		From			То			
Line(s)	A-Line	Numbe	er			ation(s)	A99 (Shady Grove Yard) +/-			A99 (Shady Grove Yard) +/-				
	Head Car Number		N	Number of Cars			Me		Meter – AEMC Model & Model 1060 (mega ohm), VOM (Fluke					
Vehicles	N/A			N/A		Equipment		123B), AAR W	/rench, Test	rench, Test Jumpers		,, ( )		
Description						Number of Defects			0					

<sup>&</sup>lt;sup>1</sup> The rail transit agency must provide WMSC with the necessary evidence (e.g. maintenance work order system records, photos, documentation, records, data, or other evidence) to close out the Remedial Action. Closeout of Remedial Actions may also be subject to ongoing WMSC verification inspections to ensure corrections are sufficient and effective.

Inspector in Charge – Signature		Date
KEMMERY E. KENDRICK		11/15/19 – 11/16/19
Inspector in Charge – Name	Inspection Team	
KEMMERY E. KENDRICK	WASHINGTON METRORAIL SAFETY COMMISSION	

Form WMSC-IR-1 Version date: 10/5/18



# **Inspection Form**

### Form WMSC-IR-1

## Washington Metrorail Safety Commission

	WMSC personnel under the protection of a WMATA RWIC performed cable	Recommended Finding?	NO
	meagering testing. The location was reported as A99 (Shady Grove Yard).	Remedial Action Required?	NO
	<ol> <li>O145(am) – Permission requested, and granted by Yard Tower OPS, testing went underway.</li> <li>Testing one (1) 37 Signal Conductor Cable (standard wire #14 AWG), with 16 spares.</li> <li>Affecting Signals: 92, 142, 144, and 148</li> <li>Disrupting: SCX-120 (Signal Control AC Power), UCX-120 (Negative), UBX-120 (Positive), and 16 Spares.</li> <li>Team crew of 5 – 2 inside the TRC-1 and 3 members outside at the corresponding Junction Box, approximately 300 – 500 feet outside in the yard.</li> <li>Both sets of team members inspected cables looking for signs of damage and deterioration. Outside crew members noticed the normal corrosion on outside hardware and post connections (due to weather changes)</li> <li>Crew members loosened lock nuts and pulled back straps to test on both ends of the cable.</li> <li>1st step – Resistance Testing of 37 conductor – Test good</li> <li>3 and final step Cable to Cable Testing (cross Meg) 2½ process</li> <li>Testing complete – All cable connections restored, Tower Operator and ATC Production Team test all affected circuits and signals for proper lunar verification that systems were returned to normal functioning operation.</li> <li>Testing complete – Team remained on scene for 2 train moves over affected circuits.</li> <li>Testing completed approximately 0530 (am)</li> </ol>	Recommended Reinspection?	NO
Remedial Action	Cable Testing Production Team has approximately 5 to 6 members who have the result yard tracks within WMATAs system.  With 99% of the mainline tested, this crew have yet to complete 400 additional cable testing complete as of October 2019 (started in 2011), the testing is due to begin on	es (within all yards) by years end. W	
	This production crew could use approximately 5 to 6 additional members (creating a regulatory testing requirements of this type, for this system.	an additional team) to keep up with	FRA 10-year

Photos:...

Form WMSC-IR-1 Version date: 10/5/18